

Mercedes Current Draw or Turn On/Off Pop

If you are experiencing any of the following symptoms after the installation of an amplifier retention piece in a 2004-2008 Mercedes, you can follow the steps outlined in this document to correct them.

Symptoms

- Higher than acceptable current draw or a dead battery.
- Factory amplifier staying on when vehicle is not on.
- Turn on pop or squeal.
- Turn off pop or squeal.

Solution

Cut the yellow wire going to the 10Pin Molex Connector that plugs in to the “C2-MOST-25-MC” decoder and connect accessory power from the STK756 interface to the end going in to the decoder.

