



INTERFACE FEATURES

- Provides accessory power (12-volt 10-amp)
- Retains R.A.P. (Retained Accessory Power)
- Provides wires for multimedia radios (park brake, reverse, speed sense)
- Used in non-amplified models, or when bypassing a factory amplifier
- Used in models without OnStar[®] or when not retaining OnStar[®]
- Retains all warning chimes
- High level speaker input
- Retains balance and fade
- Provides illumination output
- Micro-B USB updatable

GM Chime Interface

2014-2020

Visit AxxessInterfaces.com for more detailed information about the product and up-to-date vehicle specific applications.

INTERFACE COMPONENTS

- AXDI-GMLN9 interface
- LD-LCLAN-09 harness

CHEVROLET

Colorado (1)	2015-2018
Equinox(1).....	2018
Malibu (2).....	2016-2018
Silverado (3)	2015-2018
Silverado 1500 (3)	2014-2018
Silverado 2500/3500 (3).....	2015-2019
Silverado LD (1)	2019
Suburban.....	2015-2020
Tahoe.....	2015-2020

The RPO code is located in the Service Parts Identification sticker

GMC

Canyon (1).....	2015-2018
Sierra (3)	2015-2018
Sierra 1500 (3)	2014-2018
Sierra 2500/3500(3).....	2015-2019
Sierra Limited (1).....	2019
Yukon / Yukon XL.....	2015-2020

(1) With RPO code 105 or 106

(2) With radio code IP1

(3) With radio code 103, 105, or 106

SALES 386-257-2956

REV. 9/14/23