



# AXSP-HK with AXDIS-HK2 No Audio | TECH TIP

*AXSP-HK of the jumpers that need to be checked if they have no audio*

Open case to gain access to the circuit board, to complete the steps below to correct the issue.



Jumper 1 needs to have 2 & 3 connected, nothing on 1  
Jumper 2 needs to have 1 & 2 connected, nothing on 3

